

TECHNICAL DATASHEET

Silicone Transfers



www.ja-int.com | +44 (0)1790 752 757 J&A (International) Ltd. Insignia House, Vale Road, Spilsby, Lincolnshire PE23 5HE

Silicone Transfers



TECHNICAL DATASHEET

www.ja-int.com

APPLICATION

Temperature (°C):150°CTemperature (°F):302°FTime:10 secondsPressure:Medium42.7 - 56.9 psi / 2.9 - 3.9 bar / 3.0 - 4.0 kg/cm2Carrier Release:Cold peelHeat seal again for 5 seconds after removing the carrier

LAUNDERING

Suitable for domestic wash up to 60°C Can be tumble dried on the low setting Ironable only inside out Do not dry-clean Do not bleach

HANDLING AND STORAGE

Store in a damp-free environment at a stable temperature of ~20°C Keep away from direct sunlight No personal protection equipment is required in handling and storage Do not attempt to apply any transfer that has been removed from its carrier

**Any furnes created by this transfer during application are harmless. However, modern garment materials can be coated and finished in many different ways; some of which may alter their application and health & safety requirements. We recommend thorough checking and testing of any garment material to determine the correct requirements before application.